


- Check the taper angle of taper bar/ taper plug gages/Morse taper/ISO taper etc. The run out can be checked as well
- Sine bar accuracy (when $\alpha=30^\circ$): ± 5 seconds

CAN BE CUSTOMIZED



4157-200

TAPER INSPECTION INSTRUMENT



Code	Center height (H)	Center distance (L)
4157-200	65mm	200mm