



SHANK RUNOUT TESTERS


measure radial runout of shank




measure radial runout of collet



measure radial runout of cutter




measure radial runout of end mill



4771-30

- Measure the radial runout of shanks, collets and cutting tools
- Optional accessory: dial test indicators, magnetic stands

Code	Taper	Accuracy
4771-30	BT30	1µm
4771-40	BT40	1µm
4771-50	BT50	1µm



standard shank (included)

